Arcade Films Games General Music

System11 – blog Personal Tech / Repair

Home / Arcade • Tech / Repair / Repair – Irem games and leaking capacitors, it's real.

Repair – Irem games and leaking capacitors, it's real.

Author: James Category: Arcade, Tech / Repair 29 Mar 14

If you saw my post a while back about the very poor condition Undercover Cops which required a lot of repair work due to leaking capacitors, you'll have seen the damage they can do.

Well today I picked up a new game which I'll post in a new arrivals shortly, but yet again it was an Irem game with leaking capacitors, luckily the acid hadn't gone past the legs yet so I caught it in time to avoid any damage to the rest of the game. I'm seeing this all the time on a specific set of boards, M92, M97 and M107 games which use metallic brown ELNA capacitors.

That's games like In The Hunt, R-Type Leo, Fire Barrel, Undercover Cops and a variety of other expensive games.

If you own one of these games with brown capacitors, it will suffer serious damage WHEN these start leaking, not IF.

I know purists out there don't like things being changed from the factory, and I understand that, and I'm not the kind of guy who recaps entire monitor chassis just because it seems like a good idea. Seriously though, with these you are playing with fire. On the game I just checked 6 of 14 were leaking, all different sizes too so it's not like just one type go bad.

Replace them. I know they may look perfect now but they won't in due course. Just get it out of the way and then you won't have to worry about it anymore. If you remove them before the acid corrosion starts you'll be able to do a nice job, later on it's very hard to get corroded areas of PCB hole to really flow properly.

PROJECTS

- Arcade art scanning project
- Galaxy Force upright project

CATEGORIES

- Arcade
- Films
- Games
- General
- Music
- Personal
- Tech / Repair

RECENT POSTS

- Art scans update Moumatenaino (Next Gen DVD System vol 3)
- Visit to Whipsnade Zoo
- Art scans update Cosplay Tengoku (Super-CD)
- Nichibutsu High Rate DVD System game captures (NSFW)
- Art scans update Hopper Robo / 19XX

0 1 " "	
Search the site	

Aside from the flush fit ones (couple on each game), just cut the old ones off at the legs for a safe and easy removal later. If you try to remove the whole thing at once by heating each leg in turn and pulling it out, there's a decent chance of damaging the hole. You will need the following parts:

M107

```
470uf / 25v - C202

100uf / 25v - C210, C245

100uf / 6.3v - C204, C205

47uf / 16v - C206, C212

1uf / 50v - C201, C211, C216, C219, C220, C221, C222
```

M92

```
470uf / 25v - C202

220uf / 10v - C203

100uf / 25v - C209, C236

47uf / 16v - C213

22uf / 25v - C204

1uf / 50v - C201, C210, C215, C216, C217, C218, C219
```

<u>M97</u>

```
470uf / 25v - C203

220uf / 10v - C201

100uf / 25v - C210

47uf / 16v - C209

22uf / 25v - C204

1uf / 50v - C202, C214, C216
```

Related Posts



Teenage Mutant Ninja/Hero Turtles RAM fault



New arrivals 08/06/15 by James

LINKS

- Repair Log
- Twitter
- For Sale List
- Shmups Forum
- UKVAC Forum

META

- Log in
- Entries RSS
- Comments RSS
- WordPress.org

ABOUT ME

I've been playing arcade and home videogames since the late 70s, I'm seriously into films of all ages and genres, many kinds of music (especially late 70s rock) and wristwatches. I'm a sysadmin by trade but on the journey into management, for my sins I currently run/host the Shmups forum but other than that I don't like to take my work home with me.

System11 – blog Copyright © 2017.

Theme by MyThemeShop